

SEE 3433 (version: 4Mei)
 Solution for Final Examination
 Semester: 2010/11-02

Question 1: Electromechanical Energy Conversion

(a) Production of torque in a singly excited and doubly excited system

6 marks

In a singly excited system,

$$T = \frac{1}{2} i^2 \cdot \frac{d}{d\theta} L(\theta)$$

The torque is produced because of variation of self-inductance with rotor position. This is also called reluctance torque.

In a doubly excited system,

$$T = \frac{1}{2} \cdot i_1^2 \cdot \frac{d}{d\theta} \cdot L_{11}(\theta) + \frac{1}{2} \cdot i_2^2 \cdot \frac{d}{d\theta} \cdot L_{22}(\theta) + i_1 \cdot i_2 \cdot \frac{d}{d\theta} \cdot L_{12}(\theta)$$

The first two terms in the equation represent torques produced because of self-inductance with the rotor position. These torques are the same torque produced in a singly excited system. The third term represents torque produced by the variation of the mutual inductance between the stator and the rotor winding. This torque uniquely belongs to a doubly excited system.

(b) $i = k \cdot \lambda^2 \cdot e^{2x}$

6 marks

$$W_f = \int i \, d\lambda = \int 6 \cdot \lambda^2 \cdot e^{2x} \, d\lambda = 6 \cdot \frac{\lambda^3}{3} \cdot e^{2x} = 2 \cdot \lambda^3 \cdot e^{2x}$$

$$f_m = \frac{-\delta}{\delta x} W_f(\lambda, x) \quad f_m = 4\lambda^3 \cdot e^{2x}$$

$$\lambda := 2 \quad x := 1$$

$$f_m := 4\lambda^3 \cdot e^{2x} \quad f_m = 236.45$$

(c) Calculation

(i) $T = i_1 i_2 \cdot \frac{d}{d\theta} L_{12}(\theta)$

2 marks

(ii) $i_1 = 4 \quad i_2 = 8 \sin(10t) \quad L_{12} = 0.5 \cdot \cos(\theta)$

5 marks

$$T = 4 \cdot 8 \cdot \sin(10t) \cdot \frac{d}{d\theta} 0.5 \cos(\theta)$$

calculator:

$$T = -16 \cdot \sin(10 \cdot t) \cdot \sin(\theta)$$

$\sin(60\text{deg}) \cdot 16 = 13.856$

$$T = -13.856 \cdot \sin(10 \cdot t)$$

Because of T consists only sine function, the average torque is zero.

$$(iii) \quad T = 4 \cdot 8 \cdot \sin(10t) \cdot \frac{d}{d\theta} 0.5 \cos(\omega_m \cdot t + \delta)$$

6 marks

$$T = 4 \cdot 8 \cdot \sin(10 \cdot t) \cdot \frac{d}{d\theta} \cdot 0.5 \cdot \cos(10 \cdot t + 60)$$

$$T = -16 \cdot \sin(10 \cdot t) \cdot \sin(10 \cdot t + 60)$$

$$T = 8 \cdot \cos[10 \cdot t - (10 \cdot t + 60)] - 8 \cos[10 \cdot t + (10 \cdot t + 60)]$$

$$T = 8 \cdot \cos(-60) - 8 \cos(20 \cdot t + 60)$$

$$T_{ave} := 8 \cdot \cos(-60deg) \quad T_{ave} = 4 Nm$$


Question 2: DC Machine (generator)

(a) $V_t - I_a$ characteristics of DC generator

6 marks

In cumulative compound generator, the field of the shunt and series winding add each other. With increasing armature current the field due to series winding increases. This may compensate the drop in terminal voltage due to $I_a R_a$ drop and armature reaction. Then, the terminal voltage may rise.

In differential compound generator, the field of the shunt and series winding oppose each other. With increasing armature current the field due to series winding decreases. Therefore, the terminal voltage drops very quickly with increasing armature current.



(b) Calculation for generated voltage

5 marks

$$p := 6 \quad N := 300 \quad a := 2 \quad \phi := 0.025 \quad N_m := 1000$$

$$K_a := \frac{N \cdot p}{\pi \cdot a} \quad K_a = 286.479 \quad \omega_m := \frac{N_m}{60} \cdot 2\pi$$

$$(i) \quad E_a := K_a \cdot \phi \cdot \omega_m \quad E_a = 750 \text{ V}$$

$$(ii) \quad I_a := 25 \cdot a \quad I_a = 50 \text{ A} \quad P := E_a \cdot I_a \quad P = 37.5 \text{ kW}$$

(c) Calculation for DC generator

(i) Diagram of compound DC machine

3 marks

Insert Diagram of Compound DC Machine here

- (ii) Draw a field resistance line that intersects the magnetization curve at 100 V. **4 marks**

From the graph: $I_f := 0.8 \cdot A$ $E_a := 100 \cdot V$

At no load, $V_t := E_a$ $R_f := \frac{V_t}{I_f}$ $R_f = 125 \Omega$

(iii) $V_{t_NL} := 100 \cdot V$ $R_f = 125 \Omega$ $R_{sr} := 0.04 \cdot \Omega$ $R_a := 0.1 \Omega$ $N_f := 1200$
 $I_{f_AR} := 0.05 \cdot A$ **7 marks**

At full-load: $V_{t_FL} := V_{t_NL}$ $V_t := 100 \cdot V$ $I_a := \frac{10 \cdot kW}{100 \cdot V}$ $I_a = 100 A$

$I_f := 1$ $I_t := 100$ (Guess values)

Given

$$I_a = I_f + I_t \quad I_f \cdot R_f = I_t \cdot R_{sr} + V_t$$

$$\begin{pmatrix} I_f \\ I_t \end{pmatrix} := \text{Find}(I_f, I_t) \quad I_f = 0.832 A \quad I_t = 99.168 A$$

$E_a := V_t + I_t \cdot R_{sr} + I_a \cdot R_a$ $E_a = 113.967 V$

From the graph, $I_{f_eff} := 1.20 \cdot A$

$N_{sr} := 5$ (Guess value) Given

$$I_{f_eff} = I_f + \frac{N_{sr}}{N_f} \cdot I_t - I_{f_AR}$$

$N_{sr} := \text{Find}(N_{sr})$ $N_{sr} = 5.061$

Question 3: DC Machine (motor)

- (a) The terminal voltage speed control **4 marks**

The terminal voltage control is the best method to control speed of DC motors. This is because the maximum torque capability is maintained and smooth variation of speed from zero to base speed is guaranteed. This method, however, is relatively expensive because it requires a variable DC supply.

- (b) The effect of armature reaction in DC motor operation **4 marks**

The effect of armature reaction is that it reduces the useful flux in the air gap. In DC motor operation, the decreasing field will cause the higher speed. It also shifts the magnetic neutral axis of the machine at which the brushes are normally placed.

(c) Calculation for DC motor

$$V_t := 100 \cdot V \quad R_a := 0.1 \cdot \Omega \quad \omega_{NL} := 800 \cdot \text{rpm}$$

(i) At no load, $I_a := 5 \cdot A$

3 marks

$$E_a := V_t - I_a \cdot R_a \quad E_a = 99.5 \text{ V} \quad E_{a_NL} := E_a$$

From the magnetization curve, for $E_a = 99.5 \text{ V}$ $I_f = 0.79 \text{ A}$

$$V_t := E_a \quad R_f := \frac{V_t}{I_f} \quad R_f = 119.63 \Omega$$

(ii) At full-load $I_a := \frac{10 \cdot \text{kW}}{100 \text{ V}}$ $I_a = 100 \text{ A}$ $I_{a_FL} := I_a$

4 marks

$$E_{a_FL} := V_t - I_{a_FL} \cdot R_a \quad E_{a_FL} = 89.5 \text{ V}$$

Without armature reaction, $\phi_{NL} = \phi_{FL}$

$$\omega_{FL} := \frac{E_{a_FL}}{E_{a_NL}} \cdot \omega_{NL} \quad \omega_{FL} = 719.598 \text{ rpm}$$

(iii) With armature reaction, $\phi_{FL} = 0.95 \phi_{NL}$

5 marks

$$\frac{E_{a_FL}}{E_{a_NL}} = \frac{0.95 \cdot \omega_{FL}}{\omega_{NL}} \quad \omega_{FL} := \frac{1}{0.95} \cdot \frac{E_{a_FL}}{E_{a_NL}} \cdot \omega_{NL} \quad \omega_{FL} = 757.472 \text{ rpm}$$

(iv) $E_a = 89.5 \text{ V}$ at 700 rpm

5 marks

$$E_{a_800} := \frac{800}{700} \cdot 89.5 \quad E_{a_800} = 102.286 \text{ V}$$

From magnetization curve 800 rpm: for $E_a = 78.313 \text{ V}$ $I_f = 0.85 \text{ A}$

$$I_{f_eff} := 0.85 \text{ A} \quad I_f := 0.79 \text{ A} \quad I_a = 100 \quad I_{f_AR} := 0.15 \text{ A}$$

$$N_{sr} := 5 \quad (\text{guess value}) \quad \text{Given} \quad I_{f_eff} = I_f + \frac{N_{sr}}{N_f} \cdot (I_a + I_f) - I_{f_AR}$$

$$N_{sr} := \text{Find}(N_{sr}) \quad N_{sr} = 2.5$$

Question 4: Induction Machine

- (a) Terminal voltage speed control is limited in operating range **3 marks**

The torque developed by an induction motor is proportional to the square of the applied voltage. By reducing the terminal voltage, the torque will reduce drastically and the capability to drive load will reduce as the same proportion. Therefore the speed of the motor may be controlled over a limited range by varying the line voltage.

- (b) Development of torque in IM and IM can not operate at synchronous speed **4 marks**

A three-phase voltage is applied to the stator of IM. This three phase voltage produces a rotating magnetic field in the stator, rotating at synchronous speed given by

$$N_s = \frac{120 \cdot f}{p}$$

The rotating magnetic field passes over the rotor conductors and induces the voltage in them. Because the conductors in the rotor are short-circuited, the current flows and causes magnetic field in the rotor too. The interaction between stator magnetic field and rotor magnetic field will produce torque.

If the induction motor was running at synchronous speed, then the rotor would be stationary relative to the rotating magnetic field and there would be no induced voltage. Then, no current would flow in the rotor's conductor and no flux would be produced. With no rotor field, the induced torque would be zero.

- Q4(c) Calculation for Induction machine

Dummy unit: $V \equiv 1$ $\text{rpm} \equiv 1$ $\Omega \equiv 1$ $\text{Hz} \equiv 1$ $\text{kW} \equiv 10^3$ $A \equiv 1$
 $\text{Nm} \equiv 1$ $\text{kVAr} \equiv 10^3$ $k \equiv 10^3$

$$V_{3\phi} := 415 \quad N_r := 950 \quad f := 50 \quad R_1 := 0.25 \quad R_2 := 0.2 \quad p := 6 \quad X_1 := 0.65 \quad X_2 := 0.6 \quad X_M := 60$$

$$V_1 := \frac{V_{3\phi}}{\sqrt{3}} \quad V_1 = 239.6 \text{ V} \quad N_s := \frac{120 \cdot f}{p} \quad N_s = 1 \times 10^3$$

$$Z_{\text{Th}} := \frac{j \cdot X_M \cdot (R_1 + j \cdot X_1)}{R_1 + j \cdot (X_1 + X_M)} \quad Z_{\text{Th}} = 0.245 + 0.644i \quad R_{\text{Th}} := \text{Re}(Z_{\text{Th}}) \quad X_{\text{Th}} := \text{Im}(Z_{\text{Th}})$$

$$V_{\text{Th}} := \frac{X_M}{\sqrt{R_1^2 + (X_1 + X_M)^2}} \cdot V_1 \quad V_{\text{Th}} = 237.03 \text{ V}$$

- (i) Line current, power factor, and input power at full load **6 marks**

At the full-load, $s := \frac{N_s - N_r}{N_s} \quad s = 0.05$

Based on the original circuit:

$$Z_1 := R_1 + j \cdot X_1 + \frac{j \cdot X_M \cdot \left(\frac{R_2}{s} + j \cdot X_2 \right)}{j \cdot X_M + \frac{R_2}{s} + j \cdot X_2} \quad Z_1 = 4.154 + 1.502i \quad |Z_1| = 4.417$$

$$\arg(Z_1) = 19.875 \text{ deg}$$

$$\text{pf} := \cos(\arg(Z_1)) \quad \text{pf} = 0.94 \quad \text{lagging}$$

$$I_1 := \frac{V_1}{Z_1} \quad I_1 = 51.011 - 18.441i \quad |I_1| = 54.241 \quad \arg(I_1) = -19.875 \text{ deg}$$

$$P_{\text{in}} := 3 |V_1| \cdot |I_1| \cdot \text{pf} \quad P_{\text{in}} = 36.666 \text{ kW}$$

(ii) Current and torque at starting 6 marks

At start, $s := 1$

$$\text{Input impedance, } Z_{\text{in}} := Z_{\text{Th}} + \frac{R_2}{s} + j \cdot X_2 \quad Z_{\text{in}} = 0.445 + 1.244i$$

$$I_2 := \frac{V_1}{Z_{\text{in}}} \quad I_2 = 61.043 - 170.779i$$

$$P_{\text{ag}} := 3 (|I_2|)^2 \cdot \frac{R_2}{s} \quad P_{\text{ag}} = 19.735 \text{ kW}$$

$$\omega_{\text{syn}} := \frac{N_s}{60} \cdot 2\pi$$

$$T_{\text{st}} := \frac{P_{\text{ag}}}{\omega_{\text{syn}}} \quad T_{\text{st}} = 188.456 \text{ Nm}$$

$$E_1 := I_2 \cdot \left(\frac{R_2}{s} + j \cdot X_2 \right) \quad E_1 = 114.676 + 2.47i$$

$$I_M := \frac{E_1}{j \cdot X_M} \quad I_M = 0.041 - 1.911i$$

$$I_1 := I_M + I_2 \quad I_1 = 61.084 - 172.691i$$

(iii) Efficiency at which the maximum developed torque occurs 6 marks

$$S_{T_{\text{max}}} := \frac{R_2}{\sqrt{R_{\text{Th}}^2 + (X_{\text{Th}} + X_2)^2}} \quad P_{\text{rot}} := 1200 \quad (\text{Rotational losses}) \quad S_{T_{\text{max}}} = 0.158$$

$$s := S_{T_{\text{max}}} \quad Z_{\text{in}} := Z_{\text{Th}} + \frac{R_2}{s} + j \cdot X_2$$

$$I_2 := \frac{V_{\text{Th}}}{Z_{\text{in}}} \quad I_2 = 93.476 - 76.882i \quad |I_2| = 121.031 \quad \arg(I_2) = -39.437 \text{ deg}$$

$$E_1 := I_2 \cdot \left(\frac{R_2}{s} + j \cdot X_2 \right) \quad E_1 = 164.645 - 41.392i$$

$$I_M := \frac{E_1}{j \cdot X_M} \quad I_M = -0.69 - 2.744i$$

$$I_1 := I_M + I_2 \quad I_1 = 92.786 - 79.626i \quad |I_1| = 122.268 \quad \arg(I_1) = -40.635 \text{ deg}$$

$$\text{pf} := \cos(\arg(I_1)) \quad \text{pf} = 0.759$$

$$\text{Air gap power:} \quad P_{\text{ag}} := \frac{3 (|I_2|)^2 \cdot R_2}{s} \quad P_{\text{ag}} = 5.572 \times 10^4 \quad \omega_{\text{syn}} := \frac{N_s}{60} \cdot 2\pi$$

$$\text{Rotor Copper loss:} \quad P_2 := s \cdot P_{\text{ag}} \quad P_2 = 8.789 \times 10^3$$

$$\text{Mechanical power:} \quad P_{\text{mech}} := (1 - s) \cdot P_{\text{ag}} \quad P_{\text{mech}} = 4.693 \times 10^4$$


$$\text{Output power:} \quad P_{\text{out}} := P_{\text{mech}} - P_{\text{rot}} \quad P_{\text{out}} = 4.573 \times 10^4$$

$$\text{Input power:} \quad P_{\text{input}} := 3 |V_1| \cdot |I_1| \cdot \text{pf} \quad P_{\text{input}} = 6.669 \times 10^4$$


$$\text{Efficiency} := \frac{P_{\text{out}}}{P_{\text{input}}} \cdot 100 \quad \text{Efficiency} = 68.564$$

Question 5: Synchronous machine

- (a) Power angle characteristics and torque characteristics 4 marks



Power angle characteristics



Torque-speed characteristics

- (b) Power factor of synchronous motor can be controlled by field current 6 marks

The power transfer equations:


$$P = 3V_t \cdot I_a \cdot \cos\phi$$

and

$$P = \frac{3 \cdot V_t \cdot E_f}{X_s} \cdot \sin\delta$$

The motor connected to infinite bus, hence

$$V_t = \text{constant}$$



For constant power operation, $I_a \cdot \cos\phi = \text{constant}$

and

$$E_f \cdot \sin\delta = \text{constant}$$

These conditions must satisfy this phasor relationship:

$$E_f = V_t - j \cdot I_a \cdot X_s$$

The excitation voltage E_f changes linearly with the field current I_f . Therefore, as I_f is changed, E_f will change along the locus of E_f and I_a will change along the locus of I_a , signifying a change in the power factor angle ϕ .

(c) Calculation

(i) Excitation voltage and the power angle **5 marks**

$$P := 10\text{k} \quad V_{3\phi} := 415 \quad \text{pf} := 0.8 \quad X_s := 10$$

$$I_a := \frac{P}{\sqrt{3} \cdot V_{3\phi} \cdot \text{pf}} \quad I_a = 17.39 \text{ A} \quad \theta := -\arccos(\text{pf}) \quad \theta = -36.87 \text{ deg}$$

$$V_t := \frac{V_{3\phi}}{\sqrt{3}} \quad V_t = 239.6 \text{ V} \quad E_f = V_t + I_a \cdot jX_s$$

$$E_f := V_t + I_a \cdot e^{j\theta} \cdot j \cdot X_s \quad E_f = 343.941 + 139.121i$$

$$|E_f| = 371.012 \text{ V} \quad \arg(E_f) = 22.023 \text{ deg}$$

$$\text{Power angle} \quad \delta := \arg(E_f) \quad \delta = 22.023 \text{ deg}$$

$$\text{Excitation voltage} \quad E_f := |E_f| \quad E_f = 371.012 \text{ V}$$

Include Phasor diagram

(ii) Reactive kVA supplied by the machine **5 marks**

$$E_{f1} := 1.15 \cdot E_f$$

$$\frac{V_t \cdot E_f}{X_s} \cdot \sin(\delta) = \frac{V_t \cdot E_{f1}}{X_s} \sin(\delta_1)$$

$$E_f \cdot \sin(\delta) = E_{f1} \cdot \sin(\delta_1)$$

$$\delta_1 := \arcsin\left(\frac{E_f \cdot \sin(\delta)}{E_{f1}}\right) \quad \delta_1 = 19.03 \text{ deg}$$

$$E_{f1} := 1.15 \cdot E_f \cdot e^{j\delta_1}$$

$$I_a := \frac{E_{f1} - V_t}{j \cdot X_s} \quad I_a = 13.912 - 16.374i \quad |I_a| = 21.486 \text{ A} \quad \arg(I_a) = -49.648 \text{ deg}$$

Power factor angle, $\theta := |\arg(I_a)|$ $\theta = 49.648 \text{ deg}$

Power factor, $\text{pf} := \cos(\theta)$ $\text{pf} = 0.647$ lagging

Reactive power, $Q := 3 \cdot |V_t| \cdot |I_a| \cdot \sin(\theta)$

$Q = 11.77 \text{ kVAr}$

Include Phasor diagram

(iii) $\delta := 90 \text{ deg}$ $E_f = 371.012 \text{ V}$ **3 marks**

$P_{\max} := \frac{3 \cdot V_t \cdot E_f}{X_s}$ $P_{\max} = 26.668 \text{ k}$

$I_a := \frac{j \cdot E_f - V_t}{jX_s}$ $I_a = 37.101 + 23.96i$ $|I_a| = 44.165 \text{ A}$ $\arg(I_a) = 32.854 \text{ deg}$

Power factor angle, $\theta := |\arg(I_a)|$ $\theta = 32.854 \text{ deg}$

Power factor, $\text{pf} := \cos(\theta)$ $\text{pf} = 0.84$ leading

Reactive power, $Q := 3 \cdot |V_t| \cdot |I_a| \cdot \sin(\theta)$

$Q = 17.222 \text{ kVAr}$

Include Phasor diagram