FIGURE 4.24 Used in the Examples 4.2 through 4.7

Magnetization Curve at 1000 rpm